Equipment issues: 2k-only equipment stops working at switchover

Why: Some old models produced between 1998 and 1999 and sold up to 2004 (8 to 14 years old) have tuner chipsets based on the preliminary 2k COFDM (up to 2000 carrier signals) standard designed for the old ONdigital/ITVDigital pay service. In 1999 the 8k COFDM global standard (up to 8000 carrier signals) was introduced and provides much more robust and reliable reception. At switchover 8k is adopted for standard definition services and therefore why old 2k-only models will no longer provide pictures or sound.

By connecting a modern Freeview box or recorder to their 2k-only IDTV, consumers can continue to watch digital terrestrial services on the TV screen. Look for the 'digital tick' when buying any new TV equipment this shows that it is 8K capable. Any 2k-only sets being used to just monitor pictures/sound from games machines or DVD players will continue to work as before.

The list below lists all known 2k-only models as confirmed by manufacturers. Other models not listed may demonstrate the same no pictures/sound symptoms but due to a different cause.

Aanufacturer ONdigital		Description	Produced
	ONdigital sets	STB ported inside IDTVs	1998
Nokia	Mediamaster 9850T	Set Top Box	1998-2002
Pace	DTR730	Set Top Box	1330 2002
	DTR735	Set Top Box	
	om/global/support/digital-switchover		
Philips	DTX 6370	Set Top Box	Nov98-Aug01
	DTX 6371 DTX 6372	Set Top Box Set Top Box	n .
Pioneer	DBRT200	Set Top Box	
i ionee.	DBRT210	Set Top Box	
Sony	VTX-D500	Set Top Box	
Toshiba	DTB2000	Set Top Box	
	5152000	эсс тор вох	
reeview			
Fusion Goodmans	FRT100 GDB2	Set Top Box Set Top Box	2004 First half 2003
Pace	DTVA-T (Wedge Adaptor)	Set Top Box	2001
	DT210F	Set Top Box	2003
 See: www.nace.co	Twin (puma) om/global/support/digital-switchover	Digital TV Recorder	2003
Samsung	SIRU200i (Without M suffix)	Set Top Box	2003
Hitachi	28WDDODTN	28" IDTV	1998-2000
	32WD40DTN	32" IDTV	II.
"	D36W840DTN	36" IDTV	u .
Panasonic		28" IDTV	?
"	TX-32DT2 TX-28DT30	32" IDTV 28" IDTV	? 2002
	TX-32DT30	32" IDTV	2002
	TX-36DT30	36" IDTV	n .
	TX-36DT35	36" IDTV	2002
DI. III	TX-32DH40	32" IDTV	2003
Philips "	28DW6734 32DW6834	28" IDTV 32" IDTV	April-Oct 99
	32DW9625	32" IDTV	30.04.01
	28DW6557	28" IDTV	10.07.02
	32DW6557	32" IDTV	10.07.02
Sanyo "	CE28DFN1-B CE32DFN1-B	28" IDTV 32" IDTV	
	CE28DFN2-B	28" IDTV	2004
	CE32DFN2-B CE32DFN2BK-B	32" IDTV 32" IDTV	
	CE28DWN1-B	28" IDTV	
:	CE28DFN3-B-00 CE32DFN3-B-00	28" IDTV 32" IDTV	
	CE30LD3-B	30" IDTV	
	CE30LD3BK-B CE27LD3-B	30" IDTV 27" IDTV	
	CE23LD4-B	23" IDTV	
	CE23LD4W-B CE27LD4-B	23" IDTV 27" IDTV	
	CE27LD4BK-B	27" IDTV	
	CE32LD4-B CE32LD4BK-B	32" IDTV 32" IDTV	
	CE27LD5-B	27" IDTV	
•	CE32LD5-B	32" IDTV	
Sony	28DS60	28" IDTV	1998
	32DS60 28DS65	32" IDTV 28" IDTV	2001
	32DS65	32" IDTV	II .
"	28DX20	28" IDTV	
	32DX20	32" IDTV 28" IDTV	2000
"	28DX30 32DX30	28" IDTV 32" IDTV	2000 2000
"	28DS20	28" IDTV	1999
	32DS20	32" IDTV	1999
	KP41DS1 KP51DS1	41" IDTV 51" IDTV	1999 2000
"	KP51DS2	51" IDTV	2002
	KD28DX40	28" IDTV	2001
	KD32DX40 KD32DX100	32" IDTV 32" IDTV	2001 2002
	KD32DX100 KD32NX100	32 IDTV 32" IDTV	2002
"	KD32NX200	32" IDTV	2002
"	KD36NX200	36" IDTV	2002
Toshiba "	28WT98B	28" IDTV	Feb 2000
"	32WT98B 28ZT29B	32" IDTV 28" IDTV	Feb 2000 Nov 2003
"	32ZT29B	32" IDTV	Nov 2003 March 2004
"	36ZT29B	36" IDTV	Oct 2003
	42WT29B 50WT29B	42" IDTV 50" IDTV	May 2004 May 2004